

# Power distribution box, solid rubber

input Harting Han 16E, output 8 x Schuko, wired  
Distributor for CEE, Schuko and multicore cables



- Robust power distribution boxes
- Several distribution modes: Out - Out/Thru - Split

Major rubber power distributions are incredibly robust and 100% reliable companions for the intensive strain of road operation.

## Article

230101	Power distribution box, solid rubber, input Harting Han 16E, output 8 x Schuko, wired
230104	Power distribution box, solid rubber, input Harting Han 16E, output 12 x Schuko, 6-kanalig, wired
230105	Power distribution box, solid rubber, input CEE 16A, output 3 x 2 Schuko and 1 x CEE 16A

230102	Power distribution box, solid rubber, input Harting Han 16E, output 6 x Schuko, 1 x Harting Han 16E, wired
230103	Power distribution box, solid rubber, input Harting HsB6, Output 3 x CEE17 L+N+PE 32A, wired